System/Equipment	Cracks on AFR 22 bogies
Occurrence date	7/11/2017
Organisation	EPSF (Établissement Public de Sécurité Ferroviaire) - French NSA
Safety issue	EPSF was informed on Friday 10 November 2017 of the existence of
description	significant cracks on AFR 22 bogies.
	Given the potential seriousness of the consequences of this type of
	defect, EPSF asked national involved wagons keepers to identify
	vehicles equipped with AFR 22 bogies in their fleet and to immediately
	immobilize and control them. The results of these checks will be
	transmitted to EPSF. In the event of a defect found, EPSF will be
	informed of the actions decided by Holders and ECM to monitor these
	wagons.
	Railway undertakings holding a security certificate issued by EPSF have
	been informed of this alert too.

Examples of flaws to be detected:









