



SAFETY ALERT

SYSTEM/ EQUIPMENT	Freight wagon, auxiliary air reservoir	
SAFETY ISSUE DESCRIPTION	Freight wagon lost an auxiliary air reservoir (content: 125 l) while passing a station. No derailment and no injuries happened but the following six wagons have been damaged. The loss was caused to a poor weld on the stabilization of the reservoir. The reservoir was replaced only one month before the accident happened. While this replacement the poor constitution of the weld has not been identified.	
CIRCUMSTANCES <i>(e.g. special weather conditions)</i>	The reservoir was replaced only one month before the accident happened while the poor constitution of the welding has not been identified. The wagons were built in eastern Europe at the end of the eighty years. Presumably these welds are as old as the wagons. Due to the investigation of the NSA the keeper had checked his fleet and identified two more wagons with the same problem. These wagons had benn taken out of operation.	
REASON FOR ISSUE	It is possible that some other wagons with comparable history could be affected of that defect	
LIST OF SUPPORTING DOCUMENTS <i>(e.g. PHOTOS, LINKS)</i>	Some photos of the affected parts...	
LINKED WITH OCCURRENCE NOTIFIED TO ERA DATABASE?	Choose an item. OCCURRENCE DATE Click here to enter a date.	LINK TO ERA NOTIFICATION Click here to enter text.

ISSUER

ORGANISATION	Eisenbahn-Bundesamt; c/o Jochen Schaub; Heinemannstrasse 6; D-53175 Bonn		
CONTACT DATA		+49 228 98 26 35 7	 schaubj@eba.bund.de
ISSUE DATE	05/05/2014		