

Buffer 59T with round bufferplat...

Equipment:	Buffer 59T with round bufferplate
Subject:	Rolling stock - other
Description:	Due to wear of the locking rings in the cover of a buffer the bufferplate with the cover felt into the tracks. A following train hit the bufferplate with the cover and damaged the transponders for the signaling systems of the locomotive.
Country:	Netherlands
Issuer:	NSA
Issuing Date:	06/10/2014

Last Modified 06/10/2014 13:57 by Bart Olthoff

ERA System Informacji Bezpieczeństwa (SIS)

System/Sprzęt: **Zderzak 59T z okrągłą pochwą**

Rodzaj: Tabor kolejowy – inne

Opis: Wskutek zużycia pierścieni blokujących w pochwie zderzaka, tuleja zderzaka wraz z tarczą spadła na tory. Kolejny przejeżdżający pociąg uderzył w tę tuleję, co spowodowało uszkodzenie transponderów dla systemów sygnalizacyjnych lokomotywy.

Kraj: Holandia

Organ wydający: Krajowa Władza Bezpieczeństwa (NSA)

Data Wydania: 06.10.2014 r.